


2nd floor Fire Escape:
Landing fell-repaired by welding.
Cables attached for a little extra
Safety.



Fire escape stairs rusting away-treads separating from the frame.



2nd floor ceiling tile water damage.



2nd floor Hallway:
Hole made in ceiling. Bucket placed
under it to catch water when it rains.



Middle landing between 2nd & 3rd floor:
Wall not repairable and mold damage